

General Environmental Incident Summary

Incident: 3727 **Date/Time Notice:** 4/17/2015 0955 **DEM Incident No:**

Responsible Party: Civeo - Killdeer Lodge

Date Incident: 4/10/2015 **Time Incident:** 1155 **Duration:**

County: Dunn **Twp:** 145 **Rng:** 95 **Sec:** 21 **Qtr:** SW SW

Lat: 47.36079 **Long:** -102.79910 **Method:** Interpolation from map

Location Description: 384 106th Ave SW. Killdeer, ND

Submitted By: Steve Keenan

Affiliation: Environmental Manager

Address: 400 Inverness Parkway

City: Englewood

State: CO

Zip: 80112

Received By:

Contact Person: Steve Keenan
384 106th Ave SW
Killdeer, ND

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Grey Water Release

Description of Released Contaminant: Grey water from kitchen

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Plumbing fitting under Civeo's Killdeer Lodge failed releasing an unknown amount of grey water.

Risk Evaluation:

There's no immediate risk to personnel or the environment.

of Fatalities: 1

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Some of the grey water released infiltrated into the unfrozen layer of the ground before it could be collected.

Action Taken or Planned:

Plumbing was repaired to stop the release of water from the kitchen. Water was collected using a vacuum truck.

Wastes Disposal Location: Collected water was treated at the onsite waste water treatment facility.

Agencies Involved:

Updates

Date: 4/17/2015 ***Status:*** Reviewed - Assigned to NDDoH Division

Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary, this spill involved Gray Water. Forwarded to Division of Water Quality (Sarah Waldron).

Date: 12/29/2015 ***Status:*** Reviewed - No Action Required

Author: Waldron, Sarah

Updated Volume:

Notes:

Incident was asked about during joint inspection with EPA in July 2015. No further action required.